



PEREGRINE MANUFACTURING REPAIR PRICING

Service Description	PRICE
<i>Harness & Container Inspection</i>	\$20
<i>Disassemble Canopies</i>	\$10
<i>Wash Harness & Container</i>	\$40
Main Deployment	
<i>Replace BOC Pocket</i>	\$45
<i>Install Bridle Cover</i>	\$30
<i>Replace ROL Pocket</i>	\$45
Harness	
<i>Replace Chest Strap (left side)</i>	\$48
<i>Replace Complete Chest Strap (with existing hardware)</i>	\$70
<i>Replace Complete Chest Strap (with new hardware)</i>	\$75
<i>Resize Standard Harness</i>	\$130
<i>Replace Standard Harness (with existing hardware)</i>	\$295
<i>Replace Standard Harness (with new CAD hardware)</i>	\$350
<i>Replace Hip Ring Harness (with new CAD hardware)</i>	\$375
<i>Replace Hip Ring Harness (with new SS hardware)</i>	\$450
<i>Replace Hip/Chest Ring Harness (with new CAD hardware)</i>	\$400
<i>Replace Hip/Chest Ring Harness (with new SS hardware)</i>	\$450
<i>Replace Lateral</i>	\$150
<i>Replace Leg Pads (BOC)</i>	\$140
Container	
<i>Replace Reserve Floor Plate</i>	\$75
<i>Replace Pile Velcro On Riser Covers</i>	\$32
<i>Replace Hook Velcro On Riser Cover Tabs</i>	\$32
<i>Replace Riser Covers, Tuck Tab Style & Install Riser Cover Pockets</i>	\$160
<i>Update Reserve Pin Flaps To Tuck Tab Style</i>	\$60
<i>Replace Reserve Pin Cover Flap, Tuck Tab Style</i>	\$72
<i>Replace Main Pin Cover Flap</i>	\$40
<i>Replace Main #2 & Main Pin Cover Flaps</i>	\$75
<i>Replace Main Closing Loop Anchor</i>	\$100
<i>Update Main Closing Loop Anchor</i>	\$15
<i>Replace Mud Flap (each)</i>	\$50
<i>Replace Grommet (each)</i>	\$6
Rigging	
<i>Full Assembly, AAD, Reserve, Main & Pack</i>	\$115
<i>Assembly, AAD, Reserve & Pack</i>	\$75
<i>Reserve Repack</i>	\$65
<i>Main Repack</i>	\$8