



PEREGRINE MANUFACTURING REPAIR PRICING 8/2021

<i>Service Description</i>	
<i>Harness & Container Inspection</i>	<i>\$25</i>
<i>Disassemble Canopies</i>	<i>\$15</i>
<i>Wash Harness & Container</i>	<i>\$65</i>
<i>Harness Repairs:</i>	
<i>Replace Chest Strap (left side)</i>	<i>\$70</i>
<i>Replace Complete Chest Strap (with existing hardware)</i>	<i>\$70</i>
<i>Replace Complete Chest Strap (with new hardware)</i>	<i>\$105</i>
<i>Resize Standard Harness</i>	<i>\$160</i>
<i>Replace Standard Harness (with existing hardware)</i>	<i>\$325</i>
<i>Replace Hip Ring Harness (with new SS hardware)</i>	<i>\$475</i>
<i>Replace Hip/Chest Ring Harness (with new SS hardware)</i>	<i>\$475</i>
<i>Replace Lateral</i>	<i>\$235</i>
<i>Replace Leg Pads (Kush or Spacer) includes install</i>	<i>\$165</i>
<i>Container Repairs:</i>	
<i>Replace Reserve Floor Plate</i>	<i>\$195</i>
<i>Replace Riser Covers, Tuck Tab Style & Install Riser Cover Pockets</i>	<i>\$200</i>
<i>Replace Grommet (each)</i>	<i>\$15</i>
<i>Replace Reserve Pin Cover Flap, Tuck Tab Style</i>	<i>\$90</i>
<i>Replace Ring Junction Cover "Mud Flap" (each)</i>	<i>\$75</i>
<i>Replace BOC Pocket</i>	<i>\$65</i>
<i>Replace Side Flap Plastics (Reserve)</i>	<i>\$150</i>
<i>Replace Main Pin Cover Flap (new flap included)</i>	<i>\$90</i>
<i>Rebind Bridle Side of Container</i>	<i>\$80</i>
<i>Rigging:</i>	
<i>Master Rigger Airworthiness Inspection (per major component)</i>	<i>\$25</i>
<i>Full Assembly, AAD, Reserve, Main & Pack</i>	<i>\$135</i>
<i>Assembly, AAD, Reserve & Pack</i>	<i>\$115</i>
<i>Reserve Repack (all repack types Chest or Back)</i>	<i>\$80</i>
<i>Main Repack</i>	<i>\$10</i>